



Blythe Spirit

HUGE PRICE REDUCTION MUST SELL 'Moongara' is a beautiful timber yacht built with love in 1965 Constructed with a Bruised planking method with no caulking required. The hull is Queensland Beech planking on laminated stringy bark frames the deck is Queensland Beech over marine ply and sealed with COELAN. She is a Wonderful cruising boat and has sailed Fiji, NZ and Western pacific. She is a credit to her current owners with so many beautiful features such a quality build with beautiful lines. I saw her when she was last out of the water and couldn't help but notice her elegance. There is something very special about timber yachts they are a living thing with great character the next owner is to pick up the batten and keep her alive, a well looked after timber yacht will last forever.

Contact

Contact Adelaide Boat Sales
 Email info@adelaideboatsales.com.au
 Phone Jo Mitton 0411 022 286
 Website adelaideboatsales.com.au

Details

Reference	QB125
Price	AU \$14,500 Huge price reduction
Vessel Name	Moongara
Launch Year	1965
Length	31' 0" - 9.45m
Beam	9'6"
Draft	5'3"
Displacement	Approx 6 tonne
Keel / Ballast	Lead keel 2.5 tonne
Designer	Ln Randall
Builder	D. W. Baxter Melbourne
Hull Material	Timber Queensland Beech planking on laminated stringybark frames
Decks Material	Beech Plank
Engine	Volvo Penta MD6A Diesel
Engine Make/Model	Volvo Penta
Engine Hours	Unknown
Fuel	100 ltrs
Dinghy	Zodiac inflatable
Outboard	Mariner 3.3
Covers	Full deck covers and boom cover
Berths	4
Toilet	Yes
Refrigeration	Eutectic engine driven
Stove	Metho stove
Ground Tackle	2 x Admiralty pattern and one CQR type
Epirb	Yes in date
Life Jackets	Yes
Flares	Yes
Electrics	Charging by engine
Electronics	Garmin depth sounder, VHF radio, HF radio, Auto steering
Sail Inventory	3 x mainsail, No 1 Genoa, No 2 Genoa, No 1 jib, No 2 jib, Storm sail, small Jib, storm trisail, balloon spinnaker, Asymmetric spinnaker
Mast / Rigging	Timber mast (coelan coating)
Remarks	Particulars supplied about this vessel are as furnished by the vendor (s) and are believed to be correct but not

guaranteed. Potential buyers are advised to seek an independent survey and/or mechanical check



